

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0119

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: Toyota

Model: Land cruiser turbo diesel 2001

Subject: Engine cuts out

TEST: Check the Data codes. Are anti-theft fault codes stored? Check wiring & connector plug at injector pump for heat & vibration related damage.

CAUSE: The wiring plug connected to the injector pump can become loose or disconnected due to heat & or vibration causing the engine to stop.

Replace the terminals & fill the connector with resin.

T0119.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.