

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0132

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: Mitsubishi

Model: Magna TE 3.0L

Subject: Engine surges & lacks power

TEST: Road test vehicle, the engine surges and lacks power for no apparent reason. When acceleration from a near stop i.e.; slowing down to turn a corner. Stop the vehicle, cycle the ignition switch the vehicle would perform normally. There were no fault codes present & the fuel pressure & flow were within specifications.

FAULT: The oxygen sensor was faulty causing the engine to run lean. Disconnect the O2 sensor to confirm the fault, the engine would perform normally with the O2 sensor disconnected.

T0132.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.