

Mitsubishi CJ Lancer ABS Module

Injectronics now have available as a change over unit.

Part number: ABS0621CO

Faults: C2116 - Pump motor voltage low fault code. ABS / ASC warning lights on.
The ABS module is located on the passenger side in engine bay near the firewall.



Holden ZC Vectra 2.2L Z22SE ECM

Injectronics are now able to fully test & repair these units. Change over units are available.

Part number: 12581937CO

Faults: These units require programming to the immobiliser and variant coding. Using Tech2 scan tool & TIS software. Alternatively Injectronics can program for you provided all parts required to test are available. To test, Injectronics need key / column integration module, passenger & drivers side door modules, BCM, UEC (under hood electric centre) REC (rear electric centre) & instrument cluster.



F Series F250 7.3L V8 Turbo Diesel 2001 - 2003 ECM

Injectronics can offer a bench test and repair service for this unit.

Part number: 1C3F12a650AR (plus numerous others)

Faults: Common faults include a faulty injector driver module, high voltage output fault, faulty injector drivers.

We require the PCM and injector driver module to fully test. No programming is required as units are not immobilised type.



VE Commodore / Captiva BCM

Units are available as change over's and are in stock. Full repair service available.

Part number: 15921353CO

Faults: Brake lights stuck on

Requires SPS using Tech 2 scan tool on TIS. Alternatively Injectronics can supply pre programmed if given the VIN # and charging calibration. Call the tech or sales department for details.



Holden VY - VZ Commodore BCM

These units are now available in stock as a change over unit. Full repair service also available.

Part number: 92176588CO plus several others.

Faults include; Indicators staying on / no start.

Units comes complete with 2 x programmed key fobs. Requires programming to the vehicle using generic scan tool.

