

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0083

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: VW

Model: Transporter 1990-

Subject: Loss of gear indication display

VW Transporters have a display at the bottom of the dash cluster with PRN D321 shown. As you shift the T bar position the letter / number is highlighted to indicate what you have selected.

Injectronics have received calls from customers who have said that after performing work on a vehicle or swapping the transmission control unit they have had the display screen go all one shade and therefore the T bar selector position could not be identified.

If this is the case it is possible that the transmission ECM has a stored fault code or it has not learnt the base settings, eg throttle position sensor.

To rectify, read and erase fault code, repair any faults, reset base settings.

t0083.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.