

# Injectronics

Remanufactured Automotive Electronics Components

## TECHNICAL BULLETIN

**Document number: T0085**

*For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit [www.injectronics.com.au](http://www.injectronics.com.au), call our office on (+613) 8792 6999, or email [sales@injectronics.com.au](mailto:sales@injectronics.com.au)*

**Make: Ford**

**Model: AU Falcon**

**Subject: Service light reset**

As with EF & EL Falcons, the AU Falcon has a small light in the shape of a spanner that illuminates in the lower left hand corner of the dash panel when the vehicle is due for its next service. The procedure to remove the service light and reset it for the next service interval is simple and Injectronics recommend you follow this procedure.

1. Turn ignition on (don't start engine)
2. Hold down reset shaft for between 11 and 13 seconds
3. An audible beep will be heard after the shaft has been released to indicate that the command has been received and the light should go out.

Note: If the button is held down too long or not long enough, the spanner light will not clear.

**T0085.doc**

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.