

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0099

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: Holden

Model: Astra TS & X18XE1 Engine

Subject: Engine surges between 40-80km and light throttle to 3000 RPM

TEST: Check data codes with a scan tool, are codes P0400& P1405 evident? With the vehicle at normal operating temperature, disconnect the wiring to the EGR valve & road test vehicle noting the performance of the vehicle, does the vehicle drive OK?

CAUSE: Fault may be due to a faulty EGR valve.

Replace EGR.

t0099.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.