

# Injectronics

Remanufactured Automotive Electronics Components

## TECHNICAL BULLETIN

**Document number: T0125**

*For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit [www.injectronics.com.au](http://www.injectronics.com.au), call our office on (+613) 8792 6999, or email [sales@injectronics.com.au](mailto:sales@injectronics.com.au)*

**Make: Hyundai**

**Model: Lantra 1.6L / 1.8L DOHC**

**Subject: Poor idle quality (surges)**

TEST: Engine surges at idle, check fault codes, is AMM code 12 logged? Poor engine performance

FAULT: Incorrectly adjusted or installed camshaft timing belt.

Remove the timing belt top cover, locate & highlight the valve timing indexing marks.

Install a neon timing light to number 1 cylinder, start the engine & observe the valve timing indexing marks, both timing marks should not fluctuate, if so, readjust the timing belt & or replace the timing belt tensioner using the manufacturers recommended procedure

**T0125.doc**

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.