

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0130

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: Mitsubishi

Model: Lancer CE 1996 - 2003

Subject: Speedometer failure

Fitment of incorrect spark plugs can cause the speedometer to fail.

The vehicle manufacturer specifies the fitment of resistor type spark plugs to this model.

Fitting of standard (non resistor) type spark plugs can result in irreparable damage to the microprocessor on the speedometer circuit board, requiring the speedometer assembly to be replaced.

T0130.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.