

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0141

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: BMW

Model: ECM Part number 0260002154

Subject: Transmission in limp mode

Injectronics have found that a common occurring fault for part number 0260002154 is that the transmission intermittently goes into limp / fail safe mode and logs fault code 101 (eprom check – sum code).

This fault can be caused by one or more faulty ignition coil/s.

The vehicle needs to have the updated Bosch Ignition Coils. For further information please contact Injectronics.

T0141.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.