

*Inj*ectronics

TECHNICAL BULLETIN

FORD – FALCON – EF / AU

#T0115

Make: Ford

Model: Falcon EF / AU

Subject: Intermittently cutting out

TEST: Inspect the crank shaft harmonic balancer for alignment; inspect the crank angle sensor for damage.

FAULT: The crankshaft harmonic outer mass has moved & contacted the crank angle sensor.

Replace the crank angle sensor & harmonic balancer.