

Injectronics

TECHNICAL BULLETIN

MITSUBISHI – LANCER CE

#T0130

Make: Mitsubishi

Model: Lancer CE 1996-2003

Subject: Speedometer failure

Fitment of incorrect spark plugs can cause the speedometer to fail.

The vehicle manufacturer specifies the fitment of resistor type spark plugs to this model.

Fitting of standard (non-resistor) type spark plugs can result in irreparable damage to the microprocessor on the speedometer circuit board, requiring the speedometer assembly to be replaced.