

# Injectronics

Remanufactured Automotive Electronics Components

## TECHNICAL BULLETIN

**Document number: T0093**

*For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit [www.injectronics.com.au](http://www.injectronics.com.au), call our office on (+613) 8792 6999, or email [sales@injectronics.com.au](mailto:sales@injectronics.com.au)*

**Make: Holden**

**Model: Rodeo TF 3.2L V6 1998**

**Subject: Engine hard to start / wont start**

TEST

Cranking the engine the injectors will pulse once.

Cranking the engine for 5-10 seconds the engine may start.

The engine cranking speed is good.

FAULT

The battery supply voltage to ECM is low.

Replace the battery

**t0093.doc**

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.