

# Injectronics

Remanufactured Automotive Electronics Components

## TECHNICAL BULLETIN

**Document number: T0122**

*For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit [www.injectronics.com.au](http://www.injectronics.com.au), call our office on (+613) 8792 6999, or email [sales@injectronics.com.au](mailto:sales@injectronics.com.au)*

**Make: Holden**

**Model: Rodeo 2.6L**

**Subject: Poor fuel pump operation**

TEST: Check fuel pressure, should be 250 +/- 20 kPa.

Check voltage supply to fuel pump, should be 12V.

FAULT: Faulty fuel pump harness connection at the fuel pump, repair/replace the harness connector.

**T0122.doc**

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.