

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0135

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: Nissan

Model: Pulsar N15 1.6L (ECM part number 237101N900 or 237101N901)

Subject: Engine hard to start or will not start cold

TEST: Check start signal at pin 20 it should read 12V. Check starter fuse in the fuse box. Will the engine start when it is hot? Will the engine start with the throttle depressed?

FAULT: There is no crank-signal evident (12 volts) at the ECM pin 20, the start fuse is blown or has been installed into the vacant position near start fuse in the fuse box.

T0135.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.