

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0137

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: Daewoo

Model: Nubira 1.6L 1998

Subject: Injectors on all the time

TEST: Engine won't start after the engine has been removed & refitted, engine floods. Injectors on all the time (even with ignition off), fuel pump & main relay were operating (chattering).

FAULT: The two main ECM ground connections had been connected to the start motor supply or alternator battery sense terminal (battery 12 volts) by mistake.

Note: There was no apparent damage to the ECM due to the incorrect earth connection.

T0137.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.