

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0138

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: Toyota

Model: Tarago 2TZFE 1996-2000

Subject: Engine does not start on all cylinders

TEST: Engine has injection on one cylinder & then progresses to injection on all cylinders after about 30- 60 seconds only when cold. Will only do this on initial start up when cold, once started engine will start & run on all cylinders. There were no fault codes & ignition was evident.

FAULT: The ECM would not recognize the IGF signal though the signal was evident.

Replace igniter

T0138.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.