

Injectronics

TECHNICAL BULLETIN

VOLKSWAGEN - TRANSPORTER

#T0083

Make: Volkswagen

Model: Transporter 1990 onward

Subject: Loss of gear indication display

VW Transporters have a display at the bottom of the dash cluster with PRN D321 shown. As you shift the T bar position the letter / number is highlighted to indicate what you have selected.

Injectronics have received calls from customers who have said that after performing work on a vehicle or swapping the transmission control unit they have had the display screen go all one shade and therefore the T bar selector position could not be identified.

If this is the case it is possible that the transmission ECM has a stored fault code or it has not learnt the base settings, eg throttle position sensor.

To rectify, read and erase fault code, repair any faults, reset base settings.