

Injectronics

TECHNICAL BULLETIN

FORD – FALCON - AU

#T0112

Make: Ford

Model: Falcon AU

Subject: Engine running rough / rich

Test: Check for high fuel pressure & for blocked fuel return line at fuel pressure regulator.

Cause: Rust in injector fuel rail which becomes dislodged & blocks the pressure regulator.

Replace the injector fuel rail, fuel pressure regulator & fuel filter. Clean the Injectors.