

Injectronics

TECHNICAL BULLETIN

FORD – FALCON – AU

#T0117

Make: Ford

Model: Falcon AU

Subject: Engine miss, no injection on 2 cylinders

TEST: Road test vehicle, the engine will miss at times, no injection on two cylinders.

Fault codes evident, ignition coil failure P0531- P0354.

FAULT: Faulty ignition coil pack.

The PCM monitors the coil firing voltages to confirm the operation of the ignition system. If the PCM detects a coil or coils that repeatedly fail to energize, injection will be switched off on the same cylinders associated with the faulty coil or coils.