

Injectronics

TECHNICAL BULLETIN

HYUNDAI – GRANDEUR XG

#T0124

Make: Hyundai

Model: Grandeur XG

Subject: Poor engine performance and transmission in limp mode at time

TEST: No fault codes were evident

During stall test, injector duration was 6 milliseconds

O2 reading at tailpipe was 5%

O2 reading was 40 millivolts

FAULT: Faulty hot film air mass meter having an incorrect output signal causing the engine to run lean.