

Injectronics

Remanufactured Automotive Electronics Components

TECHNICAL BULLETIN

Document number: T0010

For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit www.injectronics.com.au, call our office on (+613) 8792 6999, or email sales@injectronics.com.au

Make: Ford


Model: EF Falcon / Fairlane / LTD (94 onward)

Subject: Ford service spanner indicator reset procedure

The instrument cluster fitted to the Ford EF Falcon / Fairlane / LTD range from 1994 onwards, had a liquid crystal display symbol in the shape of a spanner located beside the trip meter. The spanner symbol is displayed so as to remind the driver of the vehicles recommended service intervals.

To erase the service indicator symbol after a service, follow this procedure:-

1. Turn the key to the ignition on - engine off position.
2. Press the trip meter reset button and hold for 8 to 10 seconds.
3. The reset procedure is complete when a beep signal is heard and the spanner symbol is extinguished.



T0010.doc

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.