

# Injectronics

Remanufactured Automotive Electronics Components

## TECHNICAL BULLETIN

**Document number: T0121**

*For further technical information regarding testing, repairs or to search for New or Remanufactured Automotive electronic products, please visit [www.injectronics.com.au](http://www.injectronics.com.au), call our office on (+613) 8792 6999, or email [sales@injectronics.com.au](mailto:sales@injectronics.com.au)*

**Make: Holden**

**Model: Astra TS**

**Subject: Air mass meter fault**

TEST: Engine stalling, poor engine performance & transmission shift quality. Inspect ECM for fault codes, Intake Air temp sensor & AMM codes logged.

FAULT: The air mass meter ground is open circuit. The AMM ground is via the engine control unit.

Splice a wire to the yellow wire pin2 at the AMM and attach it to a good chassis ground point.

If the car now runs ok, have the E.C.M repaired or replaced.

**T0121.doc**

This publication is distributed with the understanding that the authors, editors and publishers are not responsible for the results of any actions or works of whatsoever kind undertaken on the basis of information contained in this publication, nor for any errors or omissions contained herein. The publishers, authors and editors expressly disclaim all and any liability to any person whomsoever whether a purchaser of this publication or not in respect of anything and of the consequences of anything done or omitted to be done by any such persons in reliance, whether whole or partial upon the whole or any part of the contents of this publication. Injectronics Australia Pty Ltd. © Copyright 2001.