

Injectronics

TECHNICAL BULLETIN

FORD – FALCON EF

#T0010

Make: Ford

Model: Falcon EF (94 onward)

Subject: Service spanner indicator reset procedure

The instrument cluster fitted to the Ford EF Falcon / Fairlane / LTD range from 1994 onwards, had a liquid crystal display symbol in the shape of a spanner located beside the trip meter. The spanner symbol is displayed so as to remind the driver of the vehicles recommended service intervals.

To erase the service indicator symbol after a service, follow this procedure:-

1. Turn the key to the ignition on - engine off position.
2. Press the trip meter reset button and hold for 8 to 10 seconds.
3. The reset procedure is complete when a beep signal is heard and the spanner symbol is extinguished.

