

Injectronics

TECHNICAL BULLETIN

MITSUBISHI – MAGNA TE

#T0097

Make: Mitsubishi

Model: Magna TE V6

Subject: Transmission shift fault

FAULT:

Vehicle would be in limp mode, 3rd gear. Drive vehicle approx 50 meters vehicle would then lock into 1st gear.

Stop vehicle, vehicle will shift into 3rd gear, drive vehicle & the cycle would continue again.

Scanner indicated it was in drive all the time regardless of selector position.

Codes 22 & 23 were indicated on scanner.

TEST: Check condition of fuse 7/ reverse light fuse

CAUSE: Failure of fuse 7 reverse light fuse.